



**Fig.1**




**BEST AVAILABLE COPY**


Fig. 2



**Fig. 3**




**Fig.4**




**Fig.5**

Transmission Rate Switch  
Request Sending Side




**Fig. 6**



**Fig.7**20

Register Abbreviation	Description
20a ~ C_SPEED	Display Device Transmission Capacity
	00:S100
	01:S200
	1x:S400
20b ~ P_SPEED	Current Operating State
	00:S100
	01:S200
	1x:S400
20c ~ N_SPEED	Operating State after Next Bus Reset
	00:S100
	01:S200
	1x:S400
20d ~ CHG_MODE	0:Clear for Each Bus Reset
	1:Do Not Clear for Each Bus Reset


**Fig. 8**






**Fig. 9**

Transmission Rate Switch  
Request Sending Side




**Fig.10**


Transfer Rate Switch  
Request Receiving Side




**Fig.11**



**Fig.12 (Prior Art)**



**Fig.13(Prior Art)**



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ **BLACK BORDERS**

☒ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**

☐ **FADED TEXT OR DRAWING**

☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**

☐ **SKEWED/SLANTED IMAGES**

☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**

☐ **GRAY SCALE DOCUMENTS**

☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**

☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**

☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**